

Success Stories

Customer:

Fertilizers Company, Egypt.

Equipment:

Vertical Raw Mill.

Application Date:

Jan. 2014.

Problem:

Damaged part of the Shell.

Consumable:

Gricast 1 & Gricast 31.

Material:

Cast Iron.

Application Method:

1. Damaged part of the shell of the vertical raw mill was removed and replaced by a new manufactured one.
2. A new shell plate was manufactured partially.
3. New shell was successfully installed, welded and coated.
4. Damaged shell perfectly repaired.

Photographs:

1. General View of Vertical Raw Mill.
2. Damaged Shell.
3. Installing & Welding the New Shell.
4. After Welding.
5. Application Done Perfectly.

