

# Success Stories

**Customer:**

Cement Company, Egypt.

**Application Date:**

March 2014.

**Equipment:**

Vertical Mill.

**Problem:**

Worn-out Roller Segments.

**Consumable:**

Lincor 65 & Lincor Bu.

**Material:**

Steel.

**Application Method:**

1. Cracked plates of the Mill Roller were welded.
2. Worn-out segments were rebuilt by 2 Build Up layers and 2 Hardfacing layers.

**Photographs:**

1. General View of the Mill Roller.
2. Worn-out Plate.
3. During Welding & Applying Hardfacing.
4. Application Done.

