

Success Stories

Customer:

Cement Company, Egypt.

Application Date:

March 2014.

Equipment:

Vertical Mill.

Problem:

Cracked Mill Roller.

Consumable:

Gridur 46.

Material:

Steel.

Application Method:

1. Cracked plates of the Mill Roller were welded.
2. Worn-out parts were rebuilt by 2 Build Up layers and 2 Hardfacing layers.

Photographs:

1. General View of the Mill Roller.
2. Worn-out Plate.
3. During Welding & Applying Hardfacing.
4. Application Done.

