

Success Stories

Customer:

Company, Egypt

Equipment:

Diesel Engine

Problem:

A broken part from the Engine

Consumable:

Gricast 1

Material:

Cast Iron

Application Method:

A supported part has been manufactured to fix the remain part from the engine block then welded using Gricast 1.

Photograph:

- 1- Diesel Engine Block.
- 2- Making Supporting to the broken part.
- 3- Welding Process.
- 4- Application Done.

