

# Success Stories

**Customer:**

Company, Egypt

**Equipment:**

Sleeve liner for a tug boat.

**Problem:**

Corrosion and Wear.

**Consumable:**

Grinox

**Material:**

Stainless Steel

**Application Method:**

The oil Seals caused 2 mm wears in the 5 Sleeves.  
Welding the worn out areas and after grinding.

**Photographs:**

- 1- Oil Seals Caused 2mm Wear.
- 2- Welding Process.
- 3- Worn Out Areas Have Been Welded.
- 4- After Grinding 800 € Were Saved / Piece.

