

## BELZONA CHILLER PROTECTION

### CUSTOMER

Five star hotel in Egypt

### APPLICATION DATE

April 2005

### APPLICATION SITUATION

Chiller unit from the hotel air conditioning plant

### PROBLEM

Corrosion of the tube sheet and water box.

### PRODUCTS

Belzona® 1341 (Supermetalgilde)

### SUBSTRATE

Steel

### APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet HEX-3.

### BELZONA FACTS

Long term protection was provided with minimum down time. The preparation and application arrangements did not disrupt the hotels operation as required by the management.

### PICTURES

1. The corroded water box.
2. Surface preparation.
3. Tube sheet completed.
4. Water box completed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve