
BELZONA REPAIRS RUBBER PONTOON

CUSTOMER

Amusement park - Egypt

APPLICATION DATE

December 2004

APPLICATION SITUATION

Rubber pontoon in a water ride

PROBLEM

The rubber pontoon was worn out in several areas from the effects of water and impact.

PRODUCTS

Belzona® 2121 (D&A Hi-Coat Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

BELZONA FACTS

These rubber pontoons are pushed through the lake by strong flow. It was critical and unsafe to use the pontoons in there condition. Belzona® 2121 was used to repair the worn out areas and also to protect the pontoon from future damage, saving the cost of new units.

PHOTOGRAPHS

1. General view of the rubber pontoons.
2. The worn out pontoons.
3. Surface preparation.
4. Applying Belzona® 2121 to the damaged areas.

