

TYPICAL CHILLER REPAIR WITH BELZONA

CUSTOMER

Five stars hotel in Egypt.

APPLICATION DATE

March 2003

APPLICATION SITUATION

Chiller unit from the hotels air conditioning plant.

PROBLEM

Corrosion of tube sheet and the end covers.

PRODUCTS

Belzona® 1311 (Ceramic R-Metal)

Belzona® 1321 (Ceramic S-Metal)

SUBSTRATE

Steel

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflets HEX-1,-2 & -3.

BELZONA FACTS

This is a many times repeated Belzona Application to chiller units. Both corroded tube sheets and end covers were perfectly rebuilt and provide long term corrosion protection.

PICTURES

1. The corroded tube sheet.
2. Rebuilding the division bars.
3. End cover being coated.
4. Tube sheets were protected by Belzona® 1321.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

