BELZONA®

KNOW-HOW *In Action*

Belzona® repair welding cracks in four stage flash drum

CUSTOMER
International petroleum company, Egypt.

APPLICATION DATE
May, 2008.

PROBLEM
Several cracks in the welding lines.

PRODUCTS
Belzona® 1591 (Ceramic XHT).

APPLICATION METHOD
Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1 .

BELZONA FACTS
Belzona 1591 was specified by client based on previous Belzona experience.

PHOTOGRAPHS
1. General view to the four stage flash drum.
2. Cracks are clarified in the welding line.
3. After Surface preparation.
4. Application completed.







Copyright © 2006 by Belzona International Ltd. All rights reserved. No part of this work covered by the copyrights hereon may be reproduced or used in any form or by any means - graphic, electronic or mechanical including photocopying, recording, taping, or information storage and retrieval systems - without written permission of the publisher.

BELZONA POLYMERICS LTD.
Claro Road, Harrogate, HG1 4AY, England. Tel: +44 (0) 1423 567641. Fax: +44 (0) 1423 505967.

BELZONA INC.
2000 N.W. 88 Court, Miami, Florida 33172, U.S.A. Tel: +1 (305) 594-4994. Fax: +1 (305) 599-1140.

® Belzona is a registered trademark