
BELZONA® REPAIRS PVC PUMP

CUSTOMER

Construction company - Egypt

APPLICATION DATE

September 2003

APPLICATION SITUATION

PVC dosing pumps (2)

PROBLEM

Cracked casing

PRODUCTS

Belzona® 1111 (Super Metal)

SUBSTRATE

PVC

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System leaflet CEP-6. The cracks were stabilized by drilling and widening it then filled with Belzona® 1111.

BELZONA FACTS

PVC cracks are critical problems, welding cannot be used here. Belzona stops the cracks in a short time saving the high costs of new units.

PHOTOGRAPHS

1. The crack in the PVC pump.
2. Stabilising the crack.
3. Cracks after preparation.
4. Cracks repaired.

