

Success Stories

Customer:

Asfour for Mining and Refractories Company, Egypt

Equipment:

Ball mill liner

Problem:

A Very Huge Crack

Consumable:

Grinox-29

Material:

X70-Steel.

Application Method:

Preheat the surface to a uniform temperature then welding using Grinox-29.

Photographs:

- 1- A Very Huge Crack in the Ball Mill Liner.
- 2- Preheating the Surface.
- 3- Welding Process.
- 4- Application Done.

