

Success Stories

Customer:

Cement Company, Egypt.

Equipment:

Cement fan.

Problem:

Abrasion

Consumable:

wearshield 70

Material:

Carbon steel

Application Method:

2 Cement Fans badly abraded
Areas were rebuilt and protect it with Hardfacing,

Photographs:

- 1- Cement fan.
- 2- Vanes were worn out .
- 3- Selecting only the Areas that exposed to Sever wear as an economic solution.
- 4- Application Done.

