

Success Stories

Customer:

Pilco Company, Egypt

Equipment:

Cutter For Sheet Metal.

Problem:

A broken part from the corner.

Consumable:

Gricast1

Material:

Cast Iron

Application Method:

Cutting damaged parts to make flat surface, then manufactured another parts made of iron to support the body, then fixed and welded it to the cast iron body.

Photographs:

- 1- Cutter Sheet Metal.
- 2- The Cutter Had A Fracture At Its Corner.
- 3- Supporting Plates after Fixing.
- 4- Application Done.

