

Success Stories

Customer:

Cement Company, Egypt.

Equipment:

Hasmag Gate.

Problem:

Sever Abrasion at the gates.

Consumable:

Conarc 80

Material:

Hardox 500.

Application Method:

The Main Part has been replaced Using **HARDOX - 500** Sheets and New Gates are manufactured and also new Hinge Plates are manufactured and fixed then we coated the body.

Photograph:

- 1- Hasmag Gate Overview.
- 2- Severe Abrasion in the Gate.
- 3- Warn Out Hinge Plate.
- 4- The Sheets after Welding.
- 5- Application Done.

