

Customer:

NLSupervision, Egypt.

Equipment:

Cement Mill 2

Application Date:

March 2014.

Problem:

Severe Cracks and Worn-out parts of Cement Mill Internal Body.

Consumable:

Grini 207.

Material:

Steel.

Application Method:

1. Cracked areas were preheated and completely opened.
2. Welding all cracks and worn-out parts with Grini 207.

Photographs:

1. Overview of Cement Mill 2.
2. Internal View of Cement Mill 2.
3. Preheating Surface.
4. During Welding Process.
5. Application Done.

