

# Success Stories

**Customer:**

National Cement, Egypt.

**Application Date:**

Feb. 2014.

**Equipment:**

Thrust Roller.

**Problem:**

10cm Thickness Reduction.

**Consumable:**

Grini 207.

**Material:**

Steel.

**Application Method:**

1. A 10cm reduction in diameter thickness was rebuilt by welding with Grini 207 and machined.
2. Thrust Roller was restored to its original diameter.

**Photographs:**

1. General View of Corroded Thrust Roller.
2. During Welding & Building Up.
3. After Rebuilding Half of Thickness Reduction.
4. Welding Done.
5. After Machining.

