

Customer:

National Company for Maize Products, Egypt

Equipment:

Starch Knife.

Problem:

Wear and lost sharpness.

Consumable:

Grinox 29

Material:

Stainless Steel

Application Method:

Supporting the knife to protect it from distortion and bending during welding process, Hardfacing the Knife and grinding the edge to restore its sharpness.

Photograph:

- 1- Starch Knife that exposed to wear and lost its sharpness.
- 2- Hardfacing the edge.
- 3- Grinding the edges.
- 4- Application Done.

