

Customer:

Company, Egypt

Equipment:

Steam Valve

Problem:

Wear and Oxidation All Over the Valve

Consumable:

Grinox 29

Material:

MO15 Steel

Application Method:

Welding the Steam Valve and machining to get accurate dimensions then testing the valve

Photograph:

- 1- Steam Valve Overview.
- 2- Wear and Oxidation All Over the Valve.
- 3- Welding the Steam.
- 4- The Valve Has Been Successfully Repaired.

