

# Success Stories

**Customer:**

Company, Egypt

**Equipment:**

Steel billet cutter

**Problem:**

A fracture and a lot of cracks

**Consumable:**

Jetweld LH-70 & Conarc 80

**Application Method:**

Check cracks with Dye penetrant, grooving , then applying various welding passes to support the body.

**Photographs:**

- 1- Severe cracks
- 2- Grooving
- 3- Welding the left side
- 4- Welding the right side
- 5- Application Done

