

Success Stories

Customer:

Company, Egypt

Equipment:

Lime Stone Crusher

Problem:

Cracks and wearing

Consumable:

Conarc 80 & Gridor 7

Application Method:

Grinding, then buildup using Conarc 80 and finally harfacing using Gridor 7

Photograph:

- 1- Lime stone crusher.
- 2- Cracks.
- 3- Grinding, buildup and hardfacing.
- 4- Welding done successfully.

