

Success Stories

Customer:

Titan, Egypt 

Equipment:

Clinker cooler crusher

Problem:

Abrasion

Consumable:

Lincore 65-0

Application Method:

Surface Preparation , cleaning using MEK and hardfacing process by Fluxcored Hardfacing wires.

Photograph:

- 1- Hardfacing Process.
- 2- Hardfacing Process
- 3- Application Done Perfectly

